

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 13, 18, 19 and 24, Township 2 South, Range 6 & 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

30" Hemlock bears N45W 20 lks; now 38" stump, scribe marks BT exposed.

10" Hemlock bears N60E 20 lks; now missing.

4" V. maple bears S25E 8 lks; now missing.

4" V. maple bears S80W 30 lks; now missing.

At corner found 1" iron pipe with brass cap stamped LHL LBR. CORP. T2S R7W 13 18 19 24 R6W 1951 with mound of stone around pipe, from which

RESTORED BEARING TREES

42" Fir stump bears S11W 35.9°; scribed T2S R7W S24 BT.

7" Alder bears S79°30'E 37.8°; scribed T2S R6W S19 BT RE 2311.

48" Fir stump bears N23W 74.2°; scribed T2S R7W S13 BT RE 2311.


58" Fir stump bears N24°30'E 97.7°; scribed T2S R6W S18 BT.

Placed an Oregon State Board of Forestry metal location poster on 42" Fir stump BT and marked it: Sec 24 T2S R7W Sec Cor 35.9 Ft. N11E.

Dated April 25, 1952.

These BT's were restored by _____, under my direction.

Don D. Davis
Don D. Davis Assistant Forest Engineer



Present and witnessed by _____

Richard A. Morris
Richard A. Morris Compassman

Present and witnessed by _____

Robert A. Young
Robert A. Young Chainman