

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Corner common to sections 19, 24, 25, and 30, Township 3 North, Ranges 7 & 8 West, W.M., Tillamook County, Oregon.

ORIGINAL

15" x 12" x 7" stone, now missing, from which a:

- 15" Hemlock bears N37E 65 lks; now 25" down snag out of place, exposed scribe marks T3N R7W S.
- 14" Hemlock bears S65W 100 lks; now missing.
- 20" Hemlock bears S50E 60 lks; now 22" snag, scribe marks BT exposed.
- 19" Hemlock bears N61W 64 lks; now missing.

RESTORED CORNER AND BEARING TREES

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R8W R7W S24 S19 S25 S30," 2 1/2" in ground. Raised mound of stone around corner pipe, from which a:

- 48" Fir stump bears S72W 69.4'; scribed T3N R8W S25 BT 2311.
- 60" Fir stump bears S47E 43.3'; scribed T3N R7W S30 BT.
- 72" Fir stump bears N62E 90.6'; scribed T3N R7W S19 BT.
- 49" Fir stump bears N51W 52.3'; scribed T3N R8W S24 BT.

Placed an Oregon State Board of Forestry metal location poster on original BT now 22" Hemlock snag and marked it: Sec 19 T3N R7W Sec Cor 39.6 Ft. N50W.

Dated April 8, 1952.

This corner was restored by Don D. Davis under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris Richard A. Morris Compassman

Present and witnessed by Robert A. Young Robert A. Young Chainman