

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Corner common to sections 29, 30, 31, and 32, Township 3 North, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

20" x 14" x 12" basalt stone, now missing, from which a:

- 12" Hemlock bears N58E 30 lks; now missing.
- 17" Hemlock bears S47E 33 lks; now 29" stub 18" high, exposed scribe marks 7 W S.
- 16" Hemlock bears S24W 68 lks; now 28" down stub out of place, scribe marks 7W S 31 exposed.
- 14" Hemlock bears N42W 22 lks; now 14" stub badly decayed.

RESTORED CORNER AND BEARING TREES


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R7W S30 S29 S31 S32 1952 2311," 2 1/2' in ground, from which a:

- 48" Fir stump bears N0°30'W 9.7'; scribed S30 BT.
- 56" Fir stump bears S88W 24.9'; scribed T3N R7W S31 BT.
- 36" Fir stub 10' high bears S58°30'E 41.8'; scribed T3N R7W S32 BT RE 2311.
- 63" Fir stump bears N71E 26.7'; scribed T3N R7W S29 BT.

Placed an Oregon State Board of Forestry metal location poster on 29" Hemlock stub BT and marked it: Sec 32 T3N R7W Sec Cor 21.5 ft. N47W.

Dated April 22, 1952.

This corner was restored by Don D. Davis under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris Richard A. Morris Compassman

Present and witnessed by Robert A. Young Robert A. Young Chainman