

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to sections 32 and 33, Township 2 South,  
Range 7 West, W.M., Tillamook County, Oregon

ORIGINAL

Post, now missing, from which a:

- 30" Hemlock bears S59°30'W 50 lks; now 35" snag, scribe marks 1/4 BT exposed.
- 30" Hemlock bears N65E 24 lks; now 35" snag, scribe marks BT exposed.

RESTORED CORNER AND BEARING TREES


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked  
"OREGON STATE BOARD OF FORESTRY 1/4 S32 S33 1952 2311,"  
2 1/2" in ground. Raised mound of stone around corner pipe,  
from which a:

- 90" Fir stump bears N39W 80.0°; scribed 1/4 S32 BT RE 2311.
- 78" Fir stump bears S31°30'E 37.0°; scribed 1/4 S33 BT RE 2311.

Placed an Oregon State Board of Forestry metal location poster  
on 78" Fir stump BT and marked it: Sec 32 T2S R7W 1/4 Cor  
80 Ft. S39E.

Dated April 16, 1952.

This corner was restored by Don D. Davis,  
under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris  
Richard A. Morris Compassman

Present and witnessed by Robert A. Young  
Robert A. Young Chainman