

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 3, 4, 33, and 34, T2 and 3S R7W, WM., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 30" Hemlock bears N37W 23 lks; now missing.
- 48" Fir bears N28E 61 lks, now 56" stump, exposed scribe marks S34.
- 12" Fir bears S50°30E 15 lks, now missing.
- 50" Fir bears S60W 8 lks, now 63" stump on west edge of cat road and covered with dirt.

RESTORED BEARING TREES

As a reference monument


Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY RM T2S R7W S33 S34 S4 S3 T3S Cor. 23 Ft. W 1952 2311," $2\frac{1}{2}$ " in ground, 23.0' East of corner point. Raised mound of stone around pipe.

- 42" Fir stub bears S09°30'E 101.0' from the corner point; scribed T3S R7W S3 BT.
- 20" Fir snag bears N17°30'W 35.3' from the corner point; scribed T2S R7W S33 BT RE 2311.
- 14" Fir stub 20' high bears S84W 10.4' from the corner point; scribed T3S R7W S4 BT.

Placed an Oregon State Board of Forestry metal location poster on 14" Fir stub BT and marked it: Sec 4 T3S R7W Sec Cor 10.4 Ft. N84E.

Dated August 15, 1952.

This corner was restored by Don D. Davis, under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris Richard A. Morris Compassman

Present and witnessed by Robert A. Young Robert A. Young Chainman