

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 1, 2, 11, and 12, T2N R7W, W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone 20" x 12" x 12", now in place marked with 5 notches on South and 1 on East edges, from which a:

- 12" Hemlock bears N50E 37 lks; now 12" stub, 12" high, badly burned.
- 24" Hemlock bears S42E 70 lks, now 35" stump, face burned, not all exposed.
- 30" Hemlock bears S41W 42 lks, now 35" stump, face burnt out.
- 20" Hemlock bears N68W 51 lks, now 30" stump, parts of scribe marks visible.

RESTORED CORNER AND BEARING TREES


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2N R7W S2 S1 S11 S12 1952 2311," 28" in ground. Placed original stone on North side of pipe and raised mound of stone around corner pipe, from which a:

- 18" Fir snag bears S64W 95.1'; scribed T2N R7W S11 BT.
- 30" Fir stump bears N32W 61.3'; scribed T2N R7W S2 BT.
- 21" Fir stump bears N65E 92.7'; scribed T2N R7W S1 BT.
- 36" Fir tree bears S69E 206.6'; scribed T2N R7W S12 BT RE 2311.

Placed an Oregon State Board of Forestry metal location poster on original BT now 30" Hemlock stump and marked it: Sec 2 T2N R7W Sec Cor 33.7' S68E.

Dated August 15, 1952.

This corner was restored by Richard A. Morris, under my direction. Richard A. Morris - Compassman



Present and witnessed by Robert A. Young - Chairman