

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 17, 18, 19, and 20, T2N R9W, WM., Tillamook County, Oregon.

ORIGINAL

Basalt stone 18" x 10" x 8", now missing, from which a:

- 12" Fir bears N38W 9 lks; now 16" stub 18' high.
- 12" Fir bears N54E 10 lks, now 20" green tree bears N66E, did not attempt to expose face.
- 10" Fir bears S37E 31 lks, now 30" green tree bears S33E, scribe marks 20 exposed.
- 10" Fir bears S69W 43 lks, now missing.

RESTORED CORNER AND BEARING TREES


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2N R9W S18 S17 S19 S20 1952 2311," 2 1/2' in ground. Raised mound of stone around corner pipe, from which a:

- 22" Fir bears N86W 3.5'; scribed T2N R9W S18 BT RE 2311.
- 25" Fir bears S57°30'W 28.0'; scribed T2N R9W S19 BT.

Placed an Oregon State Board of Forestry metal location poster on original BT now 30" Fir and marked it: Sec 20 T2N R9W Sec Cor 19.9 Ft. N33W.

Dated August 15, 1952.

This corner was restored by Don D. Davis, under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris Richard A. Morris Compassman

Present and witnessed by Robert A. Young Robert A. Young Chairman