

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Closing corner common to sections 4 and 5 T1S R7W, WM., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

14" Hemlock bears N70°30'W 9 lks; now 18" down snag out of place, scribe marks CC S4 and 5 exposed.

50" Hemlock bears S22W 58 lks, now 52" snag, scribe marks T1S R7W S exposed.

12" Hemlock bears S10E 106 lks, now 13" down snag out of place, scribe mark T exposed.

RESTORED CORNER AND BEARING TREES

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1N R7W S32 S5 S4 T1S R7W CC 1952 2311," 36" in ground, from which a:

63" Fir stump bears S13°30'E 71.3'; scribed CC T1S R7W S4 BT RE 2311.


84" Fir snag bears S63W 118.8'; scribed CC T1S R7W S5 BT.

Placed an Oregon State Board of Forestry metal location poster on 52" Hemlock snag and marked it: Sec 5 T1S R7W Closing Cor. 58.3 Ft. N22E.

Dated August 15, 1952.

This corner was restored by my direction.

Richard A. Morris, under
Richard A. Morris - Compassman



Present and witnessed by

Robert A. Young
Robert A. Young - Chairman