

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 12, 7, 13, and 18, T2N R7 and 8W, WM., Tillamook County, Oregon.

ORIGINAL

Basalt stone 17" x 12" x 9", marked with 4 notches on South face and 2 notches on North face and with mound of stone along side, from which a:

18" Hemlock bears N51E 79 lks; now 30" Green tree, scribe marks T2N R7W S7 exposed.

RESTORED CORNER AND BEARING TREES

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2N R8W R7W S12 S7 S13 S18 1952 2311," 2 1/2' in ground. Placed Corner stone on North edge of pipe and raised mound of stone around corner pipe, from which a:

36" Noble Fir bears N21E 26.4'; scribed T2N R7W S7 BT.

42" Noble Fir bears S78E 50.7'; scribed T2N R7W S18 BT RE 2311.

90" Fir snag bears S48°30'W 16.1'; scribed T2N R8W S13 BT.


18" Alder bears N66°30'W 75.5'; scribed T2N R8W S12 BT.

Placed an Oregon State Board of Forestry metal location poster on 36" Noble Fir BT and marked it: Sec.7 T2N R7W Sec Cor 26.4 Ft. S21W.

DATED August 15, 1952.

This corner was restored by my direction.

Richard A. Morris, under
Richard A. Morris Compassman



Present and witnessed by

Robert A. Young
Robert A. Young Chairman