

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One-quarter corner common to sections 12, and 7, T2N R7 and 8W,
WM., Tillamook County, Oregon.

ORIGINAL

Basalt stone 16" x 10" x 8", no2 in place marked 1/4 on North face,
from which a:

- 28" Fir bears East 67 lks; now 12" stub 7' high badly decayed.
- 16" Hemlock bears N71W 50 lks, now 30" Hemlock stub 25' high,
face badly decayed.

RESTORED CORNER AND BEARING TREES


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE
BOARD OF FORESTRY 1/4 S12 S7 1952 2311," 36" in ground. Placed
1/4 stone on North edge of pipe, from which a:

- 54" Fir snag bears S74E 82.2'; scribed 1/4 S7 BT.
- 52" Noble Fir bears N47W 59.0'; scribed 1/4 S12 BT RE 2311.

Placed an Oregon State Board of Forestry metal location poster
on 52" Noble Fir and marked it: Sec 12 T2N R3W 1/4 Cor 59.0 Ft.
S47E.

Dated August 15, 1952.

This corner was restored by Richard A. Morris, under
my direction. Richard A. Morris - Compassman



Present and witnessed by Robert A. Young
Robert A. Young - Chairman