

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One-quarter corner common to sections 2, and 35, T1 and 2S  
R8W, WM., Tillamook County, Oregon.

ORIGINAL

Basalt stone 14" x 10" x 8", now missing, from which a:

14" Hemlock bears N22W 26 lks; now 24" snag, scribe marks  
1/4 S BT exposed.

10" Hemlock bears S41E 34 lks, now 14" down snag, face not  
exposed.

RESTORED CORNER AND BEARING TREES

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked  
"OREGON STATE BOARD OF FORESTRY 1/4 S35 S2 1952 2311," 28"  
in ground, from which a:


18" Hemlock bears N40E 69.5'; scribed 1/4 S35 BT RE 2311.

60" Fir stump bears S82W 36'; scribed 1/4 S2 BT.

Placed an Oregon State Board of Forestry metal location poster  
on original BT now 24" Hemlock snag and marked it: Sec 35  
T1S R8W 1/4 Cor 17.1 Ft. S22E.

Dated August 15, 1952.

This corner was restored by Richard A. Morris, under  
my direction. Richard A. Morris - Compassman



Present and witnessed by Robert A. Young  
Robert A. Young - Chairman