

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 20, 21, 28, and 29, Township 1 North Range 8 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, missing, from which a:

12" Hem. bears N46°W 37 lks.; now 2 ft. stub, part of BT scribe visible.

8" Hem. bears N21°E 36 lks.; now 2 ft. stub, rotted.

5" Hem. bears S61°E 23 lks.; point falls under 4 ft. down log.

4" Hem. bears S39°W 75 lks.; missing.

RESTORED CORNER AND BEARING TREES

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1N R8W S20 S21 S28 S29 1952 2311", 30" in ground. Placed large mound of stone around pipe from which a:


5½" Fir stump bears N50°W 71.4 ft.; scribed T1N R8W S20 BT.

48" Fir snag 35 ft. high bears N29°E 60.0 ft.; scribed T1N R8W S21 RE 2311 BT.

Rock outcrop 10 ft. x 15 ft. x 20 ft. high on ridge bears S11°30'E 180.0 ft.; no markings.

Dated August 22, 1952

Restored by



Present and witnessed by

Arnold G. Gibson
Arnold G. Gibson Assistant Engineer

Present and witnessed by

Jack Hann
Jack Hann

Present and witnessed by

Jack Wanek
Jack Wanek

Present and witnessed by

Gerald Smith
Gerald Smith