

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 19, 20, 29, and 30, T1N R8W, WM., Tillamook County, Oregon.

ORIGINAL

Stone 12"x12"x10" in place, 2 notches on South and 5 notches on East side from which a:

16" Hemlock bears N38W 67 lks.; now 2 Ft. Rotted stump, part of T scribe visible.

10" Hemlock bears N19E 65 lks.; now missing.

30" Hemlock bears S32W 39 lks.; now 32" stub 10' high, T scribe visible.

28" Hemlock bears S73E 77 lks.; stump hole remaining.

RESTORED CORNER AND BEARING TREES

Set 1 1/2"x36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1N R8W S19 S20 S29 S30 1952 2311," 30" in ground. Placed mound of stone around pipe from which a:


72" Cedar stump bears S81W 47.5 Ft.; scribed T1N R8W S30 RE 2311 BT.

72" Fir snag bears S2W 40.5 Ft.; scribed S30 BT.

Boulder 6 Ft. x 7 Ft. 30" above ground bears N61E 54.0 Ft.; marked X B0 on top.

Dated August 15, 1952.

This corner was restored by



Present and witnessed by Arnold G. Gibson  
Arnold G. Gibson - Assistant Engineer

Present and witnessed by Jack Henn  
Jack Henn

Present and witnessed by Jack Wanek  
Jack Wanek

Present and witnessed by Gerald Smith  
Gerald Smith