

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One-quarter corner common to sections 3, and 10, T2N R7W, WM., Tillamook County, Oregon.

ORIGINAL

Basalt stone 15" x 13" x 8", found out of place. Replaced at true point from which a:

- 36" Hemlock bears S26E 52 lks; now 52" snag badly decayed, with face rotted out.
- 30" Hemlock bears N30E 62 lks, now 40" Hemlock stump, part of scribe mark exposed.

RESTORED CORNER AND BEARING TREES


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked " OREGON STATE BOARD OF FORESTRY 1/4 S3 S10 1952 2311," 36" ground. Placed 1/4 stone on North side of pipe and raised mound of stone around corner pipe, from which a:

- 42" Fir stump bears N71W 32.5°; scribed 1/4 S3 BT RE 2311.
- 36" Fir stump bears S5E 78.3°; scribed 1/4 S10 BT.

Placed an Oregon State Board of Forestry metal location poster on 42" Fir stump and marked it: Sec 3 T2N R7W 1/4 Cor 32.5Ft. S71E.

Dated August 15, 1952.

This corner was restored by Richard A. Morris, under my direction. Richard A. Morris - Compassman



Present and witnessed by Robert A. Young - Chairman