

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 13 and 24, Township 3 North,
Range 9 West, W.M., Tillamook County, Oregon

ORIGINAL

Post, now missing, from which a:

- 36" Spruce bears N48W 65 lks; now roots in place, tree down hill badly rotted.
- 75" Fir bears S46W 48 lks; now 78" stump, face in bark, scribe visible.
- 6" Maple bears S62E 54 lks; now missing, saplings in place.

RESTORED CORNER AND BEARING TREES

Set $1\frac{1}{8}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R9W S13 S24 1952 2311," $2\frac{1}{8}$ " in ground. Raised mound of stone around corner pipe, from which a:

- 18" Fir bears N25W 49 lks; scribed T3N R9W.S13 RE 2311 BT.
- 9" Spruce bears S39W 126 lks; scribed T3N R9W S24 BT.

Placed an Oregon State Board of Forestry metal location poster on 18" Hemlock N36W 18 ft.

Dated October 31, 1952.

This corner was restored by

Louis W. Amort, Civil Engineer #2311



Present and witnessed by Arnold G. Gibson, Assistant Engineer