

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 23, 24, 25, 26, Township 2 South, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 10" Hemlock bears S58W 16 lks; now 13" stub 10 ft. high, scribe marks in cast on ground.
- 4" Vine Maple bears N40W 43 lks; now missing, sprouts in place.
- 14" Hemlock bears N71E 70 lks; now dug out, rotted.
- 24" Hemlock bears S60E 60 lks; now 24" 5" high burned and rotted.

RESTORED CORNER AND BEARING TREES


Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2S R7W S23 S24 S25 S26 1952 2311", 36 inches in ground. Raised mound of stone around corner pipe, from which a:

- 38" Fir snag 75ft. high bears S19°30'E 56.7 ft.; scribed T2S R7W S25 RE 2311 BT.
- 50" Fir snag 100 ft. high bears S49W 101.4 ft.; scribed T2S R7W S26 BT.
- 60" Fir stump bears N77W 113.5 ft.; scribed T2S R7W S23 BT.

Placed an Oregon State Board of Forestry metal location poster on 38" Fir snag BT and marked it: Sec 25 T2S R7W Sec Cor 56.7° N19°30'W.

Dated November 25, 1952.

This corner was restored by Louis W. Amort, Civil Engineer #2311



Present and witnessed by Arnold G. Gibson, Assistant Engineer