

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to sections 10 and 15, Township 3 North, Range 8 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 20" Fir bears N45E 10 lks; now 24" 4 ft. stub, $\frac{1}{4}$ cut in wood on log down hill.
- 4" Vine maple bears S41W 10 lks; now missing, clump of saplings in place.

RESTORED CORNER AND BEARING TREES

Set $1\frac{1}{2}$ " X 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S10 S15 1952 2311," $2\frac{1}{2}$ ' in ground, from which a:


- 8" Alder bears N72°W 5 ft.; scribed T3N R3W $\frac{1}{4}$ S 15 BT.
- 8" Alder bears N65°30'E 22.5 ft.; scribed RE 2311 $\frac{1}{4}$ S 10 BT.

Placed an Oregon State Board of Forestry metal location poster on 10" Alder, N14W 12 ft.

Dated October 31, 1952.

This corner was restored by

Louis W. Amort, Civil Engineer #2311



Present and witnessed by Arnold G. Gibson, Assistant Engineer