

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to sections 15 and 22, Township 1 South,
Range 6 West, W.M., Tillamook County, Oregon.

ORIGINAL.

Post, now missing, from which a:

- 24" Hemlock bears N11°15'E 80 lks; now 32" stub 5' high.
- 48" Fir bears S18W 39 lks; now 52" stump, scribe marks
BT exposed.

(Distances measured from center of original BT'S.)

RESTORED CORNER AND BEARING TREES


Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY 1/4 S15 S22 1952 2311," 2½'
in ground. Raised mound of stone around corner pipe, from
which a:

- 44" Fir stump bears N32E 68.9°; scribed 1/4 S15 BT RE 2311.
- 45" Fir stump bears S20°30'E 45.4°; scribed 1/4 S22 BT.

Placed an Oregon State Board of Forestry metal location poster
on original BT, now 52" Fir stump and marked it: Sec 22
T1S R6W 1/4 Cor 23.5 Ft. N18W.

Dated May 5, 1952.

This corner was restored by Don D. Davis
under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris
Richard A. Morris Compassman

Present and witnessed by Robert A. Young
Robert A. Young Chairman