

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to sections 2 and 35, Townships 1 & 2 South, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

8" Hemlock bears S81E 15 lks; now 10" stub 2 1/2' high, exposed scribe marks BT.

8" Hemlock bears N27W 18 lks; now 11" down stub, exposed edst of scribe marks BT.

RESTORED CORNER AND BEARING TREES

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S35 S2 1952 2311," 2 1/2' in ground. Raised mound of stone around corner pipe, from which a:


31" Fir stub 20' high bears N03°30'W 15.4'; scribed 1/4 S35 BT RE 2311.

66" Fir stump bears S29W 63.7'; scribed 1/4 S2 BT.

Placed an Oregon State Board of Forestry metal location poster on 66" Fir stump BT and marked it: Sec 2 T2S R7W 1/4 Cor 63.7 Ft. N29E.

Dated May 7, 1952.

This corner was restored by Don D. Davis under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris Richard A. Morris Compassman

Present and witnessed by Robert A. Young Robert A. Young Chainman