

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Corner common to sections 1, 2, 35, and 36, Townships 1 & 2 South, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 22" Hemlock bears N23°30'W 18 lks; now root stub.
 - 14" Hemlock bears N31E 23 lks; now 15" snag badly burnt.
 - 24" Hemlock bears S18W 34 lks; now 26" stub 5' high S22W, scribe marks BT exposed.
 - 20" Hemlock bears S68°30'E 23 lks; now root stub.
- (Distances measured from centers of original BT's.)

RESTORED CORNER AND BEARING TREES

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1S R7W S35 S36 S2 S1 T2S 1952 2311," 2½' in ground. Raised mound of stone around corner pipe, from which a:

- 50" Fir snag bears S74E 23.0'; scribed T2S R7W S1 BT.
 - 38" Fir snag bears N65W 40.8'; scribed T1S R7W S35 BT RE 2311.
 - 50" Fir stump bears S79°30'W 4.8'; scribed T2S R7W S2 BT.
- Nothing available in NE quadrant.

Placed an Oregon State Board of Forestry metal location poster on 50" Fir snag BT and marked it: Sec 1 T2S R7W Sec Cor 23.0 Ft. N74W.

Dated May 7, 1952.

This corner was restored by Don D. Davis,
under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris
Richard A. Morris Compassman

Present and witnessed by Robert A. Young
Robert A. Young Chainman