

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to sections 15 and 16, Township 1 South,  
Range 6 West, W. M., Tillamook County, Oregon.

ORIGINAL

Stone 14" x 14" x 18", now slightly out of place, marked 1/4,  
from which a:

- 60" Fir bears S47°30'E 20 lks; now 60" stump, parts of  
scribe marks visible on both burned faces.
- 15" Hemlock bears N45W 70 lks; now missing.  
(Distances measured from center of BT's.)

RESTORED CORNER AND BEARING TREES


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked  
"OREGON STATE BOARD OF FORESTRY 1/4 S16 S15 1952 2311," 2 1/2"  
in ground. Placed 1/4 stone on west edge of pipe and raised  
mound of stone around corner pipe, from which a:

- 28" Fir stump bears N19°30'W 22.4'; scribed 1/4 S16 BT RE 2311.
- 32" Fir stump bears S9E 42.8'; scribed 1/4 S15 BT.

Placed an Oregon State Board of Forestry metal location poster  
on 60" Fir stump BT and marked it: Sec 15 T1S R6W 1/4 Cor  
11.5 Ft. N47°30'W.

Dated April 24, 1952.

This corner was restored by Don D. Davis  
under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris  
Richard A. Morris Compassman

Present and witnessed by Robert A. Young  
Robert A. Young Chainman