

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Corner common to sections 1, 2, 35 and 36, Townships 2 & 3 South, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 24" Cedar bears N47W 68 lks; now 30" stub 18' high, badly burnt.
- 8" Hemlock bears S42W 27 lks; now missing.
- 24" Hemlock bears S32E 65 lks; now missing.
- 24" Hemlock bears N31E 25 lks; now 26" stump, exposed parts of scribe marks S & R.

RESTORED CORNER AND BEARING TREES


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2S R7W S35 S36 S2 S1 T3S 1952 2311," 2 1/2' in ground. Raised mound of stone around corner pipe, from which a:

- 52" Fir stump bears N74W 38.6'; scribed T2S R7W S35 BT RE 2311.
- 36" Fir stump bears N26E 50.5'; scribed T2S R7W S36 BT.
- 42" Fir stump bears S54°30'W 57.8'; scribed T3S R7W S2 BT.
- 48" Fir stump bears S07°30'E 70.2'; scribed T3S R7W S1 BT. RE 2311.

Placed an Oregon State Board of Forestry metal location poster on 52" Fir stump BT and marked it: Sec 35 T2S R7W Sec Cor 38.6 ft. S74E.

Dated April 28, 1952.

This corner was restored by Don D. Davis under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris Richard A. Morris Compassman

Present and witnessed by Robert A. Young Robert A. Young Chainman