

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to sections 14 and 15, Township 1 South,
Range 6 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

48" Fir bears N22°30'W 35 lks; now 52" stump, scribe marks
1/ exposed.

48" Fir bears S78°45'E 75 lks; now 52" stump S81°15'E,
exposed scribe mark 4.

(Distances measured from center of original BT'S.)

RESTORED CORNER AND BEARING TREES

Set 1 1/2" x 36 " galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY 1/4 S15 S14 1952 2311," 2 1/2"
in ground. Raised mound of stone around corner pipe, from
which a:

44" Fir stump bears S39°30'E 36.7'; scribed 1/4 S14
BT RE 2311.

58" Fir stump bears N64°30'W 52.9'; scribed 1/4 S15 BT.

Placed an Oregon State Board of Forestry metal location poster
on original BT, now 52" Fir stump and marked it: Sec 15
T1S R6W 1/4 Cor 21.1 Ft. S22°30'E.

Dated May 5, 1952.

This corner was restored by
under my direction.

Don D. Davis
Don D. Davis Assistant Forest Engineer



Present and witnessed by

Richard A. Morris
Richard A. Morris Compassman

Present and witnessed by

Robert A. Young
Robert A. Young Chairman