

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Corner common to sections 25, 30, 31, and 36, Township 1 South,  
Ranges 6 & 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 20" Hemlock bears S76W 53 lks; now missing.
- 28" Hemlock bears S58E 24 lks; now 40" snag, scribe marks  
6W S3 exposed.
- 20" Hemlock bears N78°30'E 73 lks; now 27" stub 10' high,  
exposed scribe marks T1S R6W S30 BT.
- 10" Hemlock bears N09°30'W 68 lks; now missing.  
(Distances measured from centers of original BT's.)

At corner found 1" iron pipe with brass cap stamped LHL LBR  
CORP T2S R7W 13 18 24 19 R6W 1951, from which

RESTORED BEARING TREES

- 18" Hemlock bears N70°30'W 62.9'; scribed T1S R7W S25  
BT RE 2311.
- 4" Hemlock bears N12°30'E 21.5'; scribed S30 BT.
- 40" Fir snag bears S22W 14.5'; scribed T1S R7W S36 BT.
- 46" Fir snag bears S58E 47.3'; scribed T1S R6W S31 BT.

Placed an Oregon State Board of Forestry metal location poster  
on 40" Fir snag BT and marked it: Sec 36 T1S R7W Sec Cor  
14.5 Ft. N22E.

Dated May 7, 1952.

These BT's were restored by Don D. Davis  
under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris  
Richard A. Morris Compassman

Present and witnessed by Robert A. Young  
Robert A. Young Chairman