

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One-quarter corner common to sections 34 and 35, T2S, R8W,  
WM., Tillamook County, Oregon.

ORIGINAL

Basalt Stone 14" x 12" x 8", now 10" x 8" x 6" marked 1/4  
on West face, from which a:

12" Hemlock bears N48E 42 lks; now 21" down log,  
scribe marks BT exposed.

6" Hemlock bears S84W 29 lks, now 12" down stub,  
scribe marks 1/4 S BT exposed.

RESTORED CORNER AND BEARING TREES

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked  
"OREGON STATE BOARD OF FORESTRY 1/4 S34 S35 1952 2311,"  
2 1/2" in ground and placed 1/4 stone on East edge of pipe.  
Raised mound of stone around corner pipe, from which a:


46" Cedar stump bears N72W 26.5°; scribed 1/4 S34  
BT RE 2311.

68" Fir stump bears N88E 59.5°; scribed 1/4 S35 BT.

Placed an Oregon State Board of Forestry metal location  
poster on 46" Cedar stump BT and marked it: Sec 34 T2S  
R8W 1/4 Cor 26.5 Ft. S72E.

Dated August 15, 1952.

This corner was restored by Don D. Davis, under  
my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris  
Richard A. Morris Compassman

Present and witnessed by Robert A. Young  
Robert A. Young Chairman