

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One-quarter corner common to sections 3 and 4, T2N R7W, W.M.,
Tillamook County, Oregon.

ORIGINAL

Basalt stone 14" x 12" x 10", now in place marked with 1/4 S
on West face, from which a:

- 16" Fir bears S50W 18 lks; now 21" snag, face burnt out.
- 4" Hemlock bears S48E 6 lks, now 26" snag, scribe marks
1/4 S BT exposed.

RESTORED CORNER AND BEARING TREES

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked
" OREGON STATE BOARD OF FORESTRY 1/4 S4 S3 1952 2311," 28" in
ground. Placed 1/4 corner stone on North edge of pipe and
raised mound of stone around corner pipe, from which a:


- 40" Fir snag bears S22°30'E 20.9'; scribed 1/4 S3 BT.
- 32" Fir snag bears N17W 13.3'; scribed 1/4 S4 BT RE 2311.

Placed an Oregon State Board of Forestry metal location poster
on original BT now 26" Hemlock snag and marked it: Sec 3 T2N
R7W 1/4 Cor 4.0 Ft. N48W.

Dated August 15, 1952.

This corner was restored by
my direction.

Richard A. Morris, under
Richard A. Morris - Compassman



Present and witnessed by

Robert A. Young
Robert A. Young - Chairman