

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 29, 30, 31, and 32, Township 2 North, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

17" x 8" x 6" basalt stone, now in place, 5 notches on East, 1 on south face, from which a:

- 28" Hemlock bears N32E 33 lks; now 30" stub 20' high.
- 20" Hemlock bears S66E 130 lks; now missing.
- 12" Hemlock bears S59°30'W 39 lks; now missing.
- 20" Hemlock bears N85W 10 lks; now missing.

RESTORED CORNER AND BEARING TREES


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2N R7W S30 S29 S31 S32 1952 2311," 2 1/2' in ground. Placed corner stone on West side of pipe and raised mound of stone around corner pipe, from which a:

- 48" Fir stub 15' high bears N39°30'E 15.3'; scribed T2N R7 W S29 BT.
- 36" Fir stump bears S03°W 100.7'; scribed T2N R7W S31 BT RE 2311.
- 52" Fir snag bears S79E 101.2'; scribed T2N R7W S32 BT.
- 72" Fir stump bears N65W 65.0'; scribed T2N R7W S30 BT.

Placed an Oregon State Board of Forestry metal location poster on 48" Fir stub BT and marked it: Sec 29 T2N R7W Sec Cor 15.3 ft. S39°30'W.

Dated June 7, 1952.

This corner was restored by Don D. Davis under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris Richard A. Morris Compassman

Present and witnessed by Robert A. Young Robert A. Young Chainman