

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 26, 27, 34, and 35, Township 2 South, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 3" Hemlock bears N40W 70 lks; now missing.
 - 72" Fir bears S32W 119 lks; now 72" snag.
 - 10" Hemlock bears S39E 63 lks; now missing.
 - 21" Hemlock bears N80E 13 lks; now 24" down log out of place, exposed scribe marks T2S R7W S26.
- (Distances measured from center of original BT'S.)

Found 1" iron pipe with brass cap stamped LHL LBR CORP T2S 27 26 34 35 R7W 1951 at corner point, from which:


RESTORED BEARING TREES

- 82" Fir snag bears N06E 73.2°; scribed T2S R7W S26 BT.
 - 96" Fir snag bears S43E 76.4°; scribed T2S R7W S35 BT RE 2311.
 - 42" Fir snag bears S57W 52.5°; scribed T2S R7W S34 BT.
- (Nothing available in NW quadrant to scribe).
Raised mound of stone around corner pipe.

Placed an Oregon State Board of Forestry metal location poster on 96" Fir snag BT and marked it: Sec 35 T2S R7W Sec Cor 76.4 ft. N43W.

Dated June 7, 1952.

This corner was restored by Don D. Davis under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris Richard A. Morris Compassman

Present and witnessed by Robert A. Young Robert A. Young Chainman