

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Witness corner for sections 23, 24, 25, and 26, Township 1 South, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 24" Hemlock bears S52E 77 lks; now 30" snag, parts of scribe marks S & R exposed. Exposed scribe marks BT.
- 8" Hemlock bears N56E 12 lks; now missing.
- 6" Hemlock bears N30W 44 lks; now missing.
- 10" Hemlock bears S31W 7 lks; now missing.

RESTORED WITNESS CORNER AND BEARING TREES

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY WC TLS R7W S23 S24 S25 S26 125 lks S 1952 2311," 2 1/2" in ground, 125 lks. north of corner point. Raised mound of stone around pipe, from which a:

- 9" Alder bears S42E 83.7'; scribed WC X BT.
- 17" Maple bears S46°30'W 16.1'; scribed WC TLS R7W S23 BT RE 2311.
- 5" Alder bears N67°30'W 12.3'; scribed WC X BT.
- 52" Fir snag bears N10°30'E 21.0'; scribed WC TLS R7W S24 BT RE 2311.

Placed an Oregon State Board of Forestry metal location poster on 17" maple BT and marked it: Sec 23 TLS R7W W C 16.8 Ft. N46°30'E.

Dated June 7, 1952.

This corner was restored by
under my direction.

Don D. Davis
Don D. Davis Assistant Forest Engineer



Present and witnessed by

Richard A. Morris
Richard A. Morris Compassman

Present and witnessed by

Robert A. Young
Robert A. Young Chainman