CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to sections 4 and 5, Township 3 South, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

12" Cedar bears N49E 43 1ks; now 30 " snag exposed, cast of parts of scribe marks 1/4 S. 6" Vine maple bears S56W 29 lks; now missing.

RESTORED CORNER AND BEARING TREES

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S5 S4 1952 2311," 21 in ground, from which a:

41" Fir snag bears N75E 83.9°; scribed 1/4 S4 BT. 44" Fir stub bears N41W 16.5"; scribed 1/4 S5 BT RE 2311.

Placed an Oregon State Board of Forestry metal location poster on 44" Fir stub BT and marked it: Sec 5 T3S R7W 1/4 Cor 16.5 Ft. S41E.

Dated June 7, 1952.

This corner was restored by ________ Don D. Davis Assistant Forest Engineer

Present and witnessed by

Richard A.

Present and witnessed by

Chainman

BOOK