

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to sections 16 and 17, Township 2 North, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

18" x 12" x 5" basalt stone, now in place, marked 1/4, from which a:

- 20" Hemlock bears S60E 56 lks; now 26" stub 20' high, badly decayed.
- 32" Hemlock bears S52W 26 lks; now 32" stub 4' high, badly decayed.

RESTORED CORNER AND BEARING TREES

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S17 S16 1952 2311," 2 1/2" in ground. Raised mound of stone around corner pipe, from which a:

- 47" Fir snag bears S46W 43.4'; scribed 1/4 S17 BT.
- 40" Fir stub 20' high bears N36E 16.4'; scribed 1/4 S16 BT RE 2311.

Placed an Oregon State Board of Forestry metal location poster on original BT now 26" Hemlock stub and marked it: Sec 16 T2N R7W 1/4 Cor 37.0 Ft. N60W.

Dated June 7, 1952.

This corner was restored by Don D. Davis under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris Richard A. Morris Compassman

Present and witnessed by Robert A. Young Robert A. Young Chainman