

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Standard section corner common to sections 31 and 32, Township 1 North, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 7" Hemlock bears S53°30'E 28 lks; now 26" stub 10' high S53°30'E 14.5, scribe marks R7W T1S S6 exposed.
 - 16" Hemlock bears S33W 59 lks; now 21" down snag, scribe marks W S6 exposed.
 - 11" Hemlock bears N71E 25 lks; now root stub under log.
 - 88" Red fir bears N66W 24 lks; now 72" stump, exposed scribe marks BT.
- (Distances measured from centers of original BT'S)

RESTORED CORNER AND REWITNESSED CORNER POINT.


Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY SC TLN R7W S31 S32 S6 T1S R7W 1952 2311," 2½' in ground, from which a:

- 70" Fir snag 50' high bears N43E 20.6'; scribed TLN R7W S32 SC BT RE 2311.
- 6" Hemlock bears N77W 98.6'; scribed S31 SC BT.

Placed an Oregon State Board of Forestry metal location poster on 70" Fir snag BT and marked it: Sec 32 TLN R7W Sec Cor 21.7 Ft. S43W.

Dated November 19, 1952.

This corner was restored by Don D. Davis
Don D. Davis Assistant Forest Engineer
under my direction.



Present and witnessed by Gerald M. Schwalen, Chairman.