

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 25, 30, 31, and 36, Township 1 North, Ranges 7 & 8 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 8" Hemlock bears N53W 32 lks; now 8" stub 3' high.
- 24" Hemlock bears N13E 42 lks; now 24' stub 3' high, N16E.
- 10" Hemlock bears S22E 55 lks; now missing.
- 4" Maple bears S33W 13 lks; now missing.

RESURVEY (Tillamook County Records)

Fir stake and large rock marked SC; now down stake scribe marks SC clearly visible and stone marked SC on south side in mound of stone.

- 10" Hemlock S22E 36.6'; now missing.
- 60" Fir S30W 49.3'; now 75" stump S33W.
- 60" Fir N24E 61.5'; now 72" snag N26E, old face burnt off.

RESTORED CORNER AND REWITNESSED CORNER POINT

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1N R8W R7W S25 S30 S36 S31 1952 2311," 2 1/2' in ground. Raised mound of stone around corner pipe, from which a:

- 66" Fir stump bears S11E 37.4'; scribed T1N R7W S31 BT.
- 72" Fir snag bears N27E 61.5'; rescribed T1N R7W S30 BT RE 2311.
- 75" Fir stump bears S31°30'W 49.3'; rescribed T1N R8W S36 BT RE 2311.


Placed an Oregon State Board of Forestry metal location poster on 66" Fir stump BT and marked it: Sec 31 T1N R7W Sec Cor 37.4' N11W.

Dated November 26, 1952.

This corner was restored by

Don D. Davis
Don D. Davis Assistant Forest Engineer

under my direction.



Present and witnessed by Robert A. Young, Compassman.

Present and witnessed by Gerald M. Schwalen, Chairman.