

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One-quarter corner common to sections 1 and 12, Township 2 North, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

14" x 10" x 7" basalt stone, now found slightly out of place, marked 1/4 on north face, from which a:

- 24" Hemlock bears S52E 34 lks.; now 36" stump, scribe marks 1/4 just visible on decayed face.
- 34" Larch bears N52E 27 lks.; now 24" snag.

RESTORED CORNER AND WITNESSED CORNER POINT

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S1 S12 1952 2311," 2 1/2" in ground. Placed one-quarter corner stone on north edge of corner pipe and raised mound of stone around corner pipe, from which a:

- 41" Noble fir stump bears N74E 34.0°; scribed 1/4 S1 BT RE 2311.
- 26" Noble fir stump bears S26°30'W 76.3°; scribed 1/4 S12 BT.

Placed an Oregon State Board of Forestry metal location poster on original BT now 24" Larch snag and marked it: Sec 1 T2N R7W 1/4 Cor 17.8 Ft. S52°W.

Dated December 4, 1952.

This corner was restored by Don D. Davis
Don D. Davis Assistant Forest Engineer
under my direction.



Present and witnessed by Robert A. Young, Compassman.

Present and witnessed by Gerald M. Schwalen, Chairman.