

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 11, 12, 13, and 14, Township 1 North, Range 8 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 14" Hemlock bears N33W 108 lks.; now missing.
- 12" Hemlock bears S46E 100 lks.; now 24" down stub out of place, exposed scribe marks TLN R8W S13.
- 12" Hemlock bears N47E 9 lks.; now 24" down snag out of place, exposed scribe marks TLN R8W.
- 18" Hemlock bears S54W 65 lks.; now 36" stub 20' high, parts of scribe marks exposed on edge of face, rest burnt out.

RESTORED CORNER AND WITNESSED CORNER POINT

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY TLN R8W S11 S12 S14 S13 1952 2311," 2 1/2' in ground. Raised mound of stone around corner pipe, from which a:

- 51" Fir snag bears N57W 152.4'; scribed TLN R8W S11 BT RE 2311.
- 42" Fir stump bears N79°30'E 123.4'; scribed TLN R8W S12 BT.
- 48" Fir stump bears S39°30'E 66.3'; scribed TLN R8W S13 BT.

Placed an Oregon State Board of Forestry metal location poster on 42" Fir stump BT and marked it: Sec.12 TLN R8W Sec Cor 124.4 ft. S79°30'W.

Dated December 10, 1952.

This corner was restored by Don D. Davis
Don D. Davis Assistant Forest Engineer
under my direction.



Present and witnessed by Gerald M. Schwalen, Chairman.