

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One-quarter corner common to sections 15 and 16, Township
2 North, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

20" x 12" x 10" basalt stone, now 9" x 8" x 6" stone marked
1/4, from which a:

18" Hemlock bears S67E 41 lks.; now 39" stump S62E,
scribe marks 4 S exposed.

15" Hemlock bears S55W 50 lks.; now 29" stump S58W,
scribe marks 4 S exposed.

RESTORED CORNER AND WITNESSED CORNER POINT

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY 1/4 S16 S15 1952 2311,"
2 1/2" in ground. Raised mound of stone around corner pipe,
from which a:

60" Fir stump bears N76E 15.4'; scribed 1/4 S15 BT RE
2311.

66" Fir snag bears S63W 80.6'; scribed 1/4 S16 BT.

Placed an Oregon State Board of Forestry metal location
poster on 60" Fir stump BT and marked it: Sec 15 T2N R7W
Sec Cor 16.0 Ft. S76°W.

Dated December 16, 1952.

This corner was restored by Don D. Davis,
Don D. Davis Assistant Forest Engineer
under my direction.



Present and witnessed by Gerald M. Schwalen, Chainman.