

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 15, 16, 21, and 22, Township 2 North, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

20" x 12" x 8" basalt stone, now missing, from which a:

- 26" Hemlock bears N56E 18 lks.; now 36" snag 25' high, exposed scribe marks BT.
- 9" Hemlock bears S88E 12 lks.; now 9" stub.
- 20" Hemlock bears S62W 88 lks.; now 24" snag 9' high, S66W 52.0, scribe marks BT exposed.
- 5" Hemlock bears N32W 130 lks.; now 12" stub 6' high, N38W 79.6, scribe marks R7W S16 exposed.

RESTORED CORNER AND WITNESSED CORNER POINT

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2N R7W S16 S15 S21 S22 1952 2311," 2 1/2' in ground. Raised mound of stone around corner pipe, from which a:

- 44" Fir snag 40' high bears N39W 77.1'; scribed T2N R7W S16 BT.
- 27" Fir snag 30' high bears S73°15'W 62.5'; scribed T2N R7W S21 BT.
- 65" Fir snag bears S14E 17.0'; scribed T2N R7W S22 BT.
- 74" Fir snag bears N82°30'E 45.8'; scribed T2N R7W S15 BT RE 2311.

Placed an Oregon State Board of Forestry metal location poster on 65" Fir snag BT and marked it: Sec 22 T2N R7W Sec Cor 17.3 Ft. N14°W.

Dated December 16, 1952.

This corner was restored by Don D. Davis
Don D. Davis Assistant Forest Engineer
under my direction.



Present and witnessed by Gerald M. Schwalen, Chainman.