

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One-quarter corner common to sections 19 and 30, T2N R7W, W1., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

48" Fir bears S17W 23 lks; now 55" stump, scribe marks BT exposed.

7" Hemlock bears N30E 19 lks; now missing.

RESTORED CORNER AND WITNESSED CORNER POINT

Set 1½"x36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S19 S30 1952 2311," 2½' in ground. Raised mound of stone around corner pipe, from which a:


43" Fir snag 25' high bears N89W 44.2'; scribed 1/4 S19 BT.

30" Fir snag bears S89E 43.4'; scribed 1/4 S30 BT RE 2311.

Placed an Oregon State Board of Forestry metal location poster on 43" Fir snag BT and marked it: Sec 19 T2N R7W 1/4 Cor 44.2 Ft. S89E.

Dated December 9, 1952

This corner was restored by Don D. Davis under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Gerald M. Schwalen, Chairman