

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 25 and 36, Township 1 North,  
Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

30" Fir bears N51W 80 lks.; now missing.

18" Fir bears S49W 18 lks.; now 27" green tree, scribe  
marks W S36 exposed.

OTHER BEARING TREES FOUND

45" Fir bears N25°30'E 39.4 ft., scribe marks 7W S30  
exposed.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked  
"OREGON STATE BOARD OF FORESTRY TLN S25 S36 R7W TLN R6W S31  
1953 2311," 28" in ground. Raised mound of stone around  
corner pipe, from which a:

45" Fir bears N85°30'W 21.7 ft.; scribed TLN R7W S25 BT  
RE 2311.

Placed an Oregon State Board of Forestry metal location poster  
on 27" Fir BT and marked it: Sec 36 TLN R7W Sec Cor 11.9 ft.  
N49°E.

Dated January 16, 1953.

This corner was restored by

*Don D. Davis*  
Don D. Davis, Assistant Forest Engineer

under my direction



Present and witnessed by Robert J. Cowan.