

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 3, 4, 33 and 34, Townships 1 & 2 North, Range 7 West, W.M., Tillamook County, Oregon

ORIGINAL

Post, now missing, from which a:

- 28" Hemlock bears N39E 73 lks.; now 33" snag, badly burned.
- 10" Hemlock bears N61W 81 lks.; now missing.
- 10" Hemlock bears S42E 43 lks.; now down 12" stub, covered by logging debris.
- 4" Maple bears S9W 51 lks.; now missing.

Restored February 26, 1952 by me.

1 1/2" x 36" galvanized iron pipe, dug up and bent by logging, from which a:

- 6 ft. Fir stump bears N75 1/2 W 34.6 ft.; scribes T2N R7W S33 BT 2311.
- 5 ft. Fir stump bears N35E 89.3 ft.; scribes T2N R7W S34 BT 2311.
- 5 ft. Fir stump bears S10E 69.3 ft.; scribes TLN R7W S3 BT (see correction below.)

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2N R7W S33 S34 S4 S3 TLN 1952 2311," 30 inches in ground, in mound of stone, and from which a:

5 ft. Fir stump bears S10E 19.3 ft.; (see above).

Oregon State Board of Forestry metal location poster on original 33" Hemlock snag BT.

Dated May 1953.

Restored by Arnold L. Gibson Assistant Engineer under my direction.



Present and witnessed by Richard A. Morris.