

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 4, 5, 8 and 9, Township 1 North, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing from which a:

- 4" Barberry bears N61W 82 lks.; now missing.
- 30" Hemlock bears N37E 72 lks.; trace of roots in place burned and rotted 6' section nearby.
- 18" Hemlock bears S62E 36 lks.; now missing.
- 14" Hemlock bears S27W 25 lks.; now 12" by 3" rotted stub.

RESTORATION by County Surveyor 1932.

Post, scribed 4 on NE, 5 on NW, 8 on SW, SC9 on SE side, from which a:

- 4" Fir bears N26E 32 feet; now missing.

RESTORED

Set 1½" x 40" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY TLN R7W S5 S4 S8 S9 1953 2311," 36 inches in ground, in place of post, and from which a:


- 66" Fir snag bears N74W 128.5 ft.; scribed TLN R7W S5 BT RE 2311.
- 52" Fir snag bears N76°30'E 108.5 ft.; scribed TLN R7W S4 BT.
- 67" Fir snag bears S20E 59.8 ft.; scribed TLN R7W S9 BT.
- 55" Fir stump bears S52W 107.3 ft.; scribed TLN R7W S8 BT.

Set County Surveyor post on North side of pipe.

Oregon State Board of Forestry metal location poster on 52" Fir snag BT. Oregon State Board of Forestry metal location poster on 4" x 4" x 48" white cedar post 18" in ground 2 ft. N. of pipe. Also poster on 63" Fir snag N4°W 65.0 ft.

Dated August 5, 1953.

Restored by Richard Morris under my direction.
Richard Morris, Compassman



Present and witnessed by Carl Vold.
Robert Schumacher.