

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section witness corner common to Sections 2, 3, 10 and 11, Township 1 North, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Stone 18 x 10 x 8, (out of place), WC and 5 notches on South and 2 notches on East, from which a:

- 16" Alder bears S75E 66 lks.; now 20", down, with old face.
- 8" Alder bears N45E 50 lks.; 2' rotted chunk on ground no other evidence.
- Other BTs missing.

RESTORATION by Oregon State Highway Commission August 10, 1942.

Found stone (no BT) with 2 notches on N. and 3 on S. marked WC. 33' N. of stone set 36" piece of inch and 1/4 pipe 20" in ground.

- 16" Alder bears N22E 4.4 ft.; marked TLN R7W BT (now 24").
- 12" Alder bears S60W 21.0 ft.; marked S10 BT (now 14") signed A.V. Benedict, RE 1960 Jan. 19, 1943.

RESTORED WITNESS CORNER

Reset witness stone 33 ft. South of highway pipe on line between 10 and 11; said line being produced from Section Corner 10, 11, 14 and 15 with transit. Original BT evidence now more accurate.

Reset 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY TLN R7W S3 S2 S10 S11 1951 199," 18 inches in ground, in mound of stone, and from which a:

- 14" Alder bears N42°30'W 55.0 ft.; scribed TLN R7W S3 199 BT. (Resetting authorized by Lyle Beyers).



Oregon State Board of Forestry metal location poster on 16" Alder BT N22E.

Set 4" x 4" x 48" white cedar post 1 ft. South of witness corner stone.

Set 4" x 4" x 48" white cedar post 2 ft. NE of corner.

Dated August 17, 1953.

Restored by Arnold G. Gibson under my direction. Arnold G. Gibson, Assistant Engineer



Present and witnessed by Richard Morris.
Carl Vold.
Robert Cowan
Robert Schumacher.

BOOK 1
PAGE 174