

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 25, 26, 35 and 36, Township 3 North, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 24" Hemlock bears N36E 24 lks.; now 20", uprooted, no marks.
- 30" Fir bears S57E 29 lks.; now 24" burned stump, scribes T3N R7W S36 BT visible.
- 30" Hemlock bears S5W 31 lks.; now 36", down, and bears S50W, scribes faintly visible.
- 10" Hemlock bears N38W 25 lks.; now missing.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R7W S25 S26 S35 S36 1953 2311," 32 inches in ground, in mound of stone, and from which a:

- 8" Fir bears N11W 87.0 ft.; scribed T3N R7W S26 BT.
- 7" Fir bears N31E 127.5 ft.; scribed T3N R7W S25 BT.
- 48" Fir stump bears S53E 70.9 ft.; scribed T3N R7W S36 BT.
- 30" Fir snag bears S45W 79.1 ft.; scribed T3N R7W S35 BT RE 2311.

Oregon State Board of Forestry metal location poster on original 30" Fir BT.


Also poster on new 30" Fir snag BT.

Also poster on white cedar post 1.5 ft. northeast of pipe.

Also poster on east bank Belding road 4 chains west.

Dated October 6, 1953.

Restored by Richard Morris under my direction.
Richard Morris, Compassman



Present and witnessed by Carl Vold.