

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 17, 18, 19 and 20, Township 1 South, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 24" Hemlock bears S55°30'W 58 lks.; now 30" stump, exposed scribes T and BT.
- 16" Hemlock bears S15°30'E 36 lks.; now missing, torn out by road construction.
- 20" Hemlock bears N11°30'W 31 lks.; now missing, torn out by road construction.
- 36" Hemlock bears N64°30'E 54 lks.; now missing.

RESTORED

Set 1½" x 40" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1S R7W S17 S18 S19 S20 1953 2311," 36 inches in ground on West edge Hembre Ridge road, in mound of stone, and from which a:

- 4" Alder bears N13W 48.8 ft.; bark scribed T1S R7W S18 BT.
- 52" Fir stump bears N49E 55.4 ft.; scribed T1S R7W S17 BT.
- 79" Fir stump bears S48E 90.1 ft.; scribed T1S R7W S20 BT RE 2311.
- 53" Fir stump bears S24W 147.7 ft.; scribed T1S R7W S19 BT.

Oregon State Board of Forestry metal location poster on 52" Fir stump BT. 4" x 4" x 48" white cedar post set 1.5 feet north of pipe.

Dated October 6, 1953.

Restored by Richard Morris under my direction.
Richard Morris, Compassman



Present and witnessed by Carl Vold.
Robert Schumacher.