

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 7 and 8, Township 2 North, Range 6 West, W.M., Tillamook and Washington Counties, Oregon.

ORIGINAL

Post, now missing, from which a:

24" Hemlock bears N40E 4 lks.; now 24" root stub 2 ft. high, face rotted off.

30" Larch bears S40 $\frac{1}{2}$ W 98 lks.; now 34" stump, scribes $\frac{1}{4}$ S visible, BT face not cut out.

RESTORATION by Crown-Zellerbach Corp. (no record)

3/4" galvanized iron pipe with lead cap marked "T2N R6W $\frac{1}{4}$ S 7/8 1952", found in place, and from which a:

28" Fir stump bears N32E 17.8 ft.; scribed T2N R6W $\frac{1}{4}$ S8 BT.

3" x 3" x 36" Fir post on West edge pipe scribed $\frac{1}{4}$ on SE side S8 on NE, S7 on SW.

Crown-Zellerbach poster on 28" Fir stump BT.

RESTORED by Oregon State Board of Forestry.

Erected mound of stone around pipe from which a:


24" Fir bears S31 $\frac{1}{2}$ E 157.6 ft.; scribed $\frac{1}{4}$ S8 BT RE 2311.

14" Fir bears S75W 54.1 ft.; scribed $\frac{1}{4}$ S7 BT.

Oregon State Board of Forestry metal location poster on 14" Fir BT. Crown-Zellerbach poster on 12" Fir stub 8 ft. high on west side Standard grade 880 ft. South.

Dated November 9, 1953.

Restored by Richard Morris, under
Richard Morris, Compassman
my direction.



Present and witnessed by Carl Vold

Robert Schumacher