

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 35 and 36  
T.2N., R.10W., W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 10" Fir bears S3°W 16 lks.; now 17" snag, scribes  
BT visible, rest unexposed.
- 5" Hemlock bears N45°E 9 lks.; now 28", scribes  
¼ S visible, rest unexposed.

RESTORED

Var. 21½°E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap  
marked "OREGON STATE BOARD OF FORESTRY ¼ S35 S36  
1955 RE 2311," 33 inches in ground, in small mound  
of stone, and from which a:

32" Spruce bears S88°W 29.9 ft.; scribed ¼ S35  
BT RE 2311.

Set 4"x4"x96" white painted Cedar post 2.5 ft. NW of pipe.  
Oregon State Board of Forestry metal location poster on  
32" Spruce BT.

Also poster on 4"x4"x72" white painted Cedar post 635.8 ft.  
S. on N. edge Miami River Highway.

Dated December 6, 1955.

Restored by Richard A. Morris under my direction.  
Richard A. Morris, Transitman



Present and witnessed by Lloyd Geraths  
Robert Sturm