

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner, common to Sections 32, 33, 4 and 5
T. 2 & 3N., R. 7W., W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone 18" x 9" x 7" (found in place with 4 notches on
E side and 2 on W side) from which a:

- 5" Hemlock bears N42°E 19 lks.; missing, tract of roots found.
- 6" Maple bears S27°E 53 lks.; missing, Vine Maple clumps in vicinity.
- 4" Maple bears S78°W 59 lks.; missing, Vine Maple clumps in vicinity.
- 5" Hemlock bears N20°W 17 lks.; now 24" uproot, roots in place, scribes T3N R7W S32 BT visible.

RESTORED

Erected mound of rock around original stone, from which a:

- 34" Maple bears N3½°E 114.6 ft.; scribed T3N R7W S33 BT RE 2311.
- 14" Maple bears S74°W 61.7 ft.; scribed T2N R7W S5 BT.
- 56" Fir stump bears N56°W 42.4 ft.; scribed T3N R7W S32 BT.
- 64" Fir stump bears S2°E 82.5 ft.; scribed T2N R7W S4 BT.

Oregon State Board of Forestry metal location poster on 64" Fir stump BT.

Set 4" x 3" x 72" white painted Cedar post 1.5 ft. SE of original stone.

Dated November 16, 1955.

Restored by Richard A. Morris under my direction.
Richard A. Morris, Transitman



Present and witnessed by Robert Sturm
Forrest Logan
Lloyd Geraths