

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 5 and 6,
T. 2N., R. 7W., W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone 15" x 11" x 9" (found in place with $\frac{1}{4}$ on W
face) from which a:

- 6" Hemlock bears S86°W 58 lks.; just roots found in place.
- 16" Hemlock bears N85°E 36 lks.; now 16" by 10 ft. high
stub, part of scribes BT remaining.

RESTORED

Erected mound of rock around corner stone, from which a:

- 46" Fir stump bears N81°E 19.2 ft.; scribed $\frac{1}{4}$ S5 BT.
- 47" Fir snag bears N67°W 20.0 ft.; scribed $\frac{1}{4}$ S6 BT RE 2311.

Oregon State Board of Forestry metal location poster on
46" Fir stump BT.
Set 4" x 4" x 72" white painted Cedar post 2 ft. NE of
corner.

Dated November 16, 1955.

Restored by Richard A. Morris under my direction.
Richard A. Morris, Transitman



Present and witnessed by Forrest Logan
Robert Sturm
Lloyd Geraths