

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 2 and 35, T. 2 and 3 N., R. 9W., W.M., Tillamook County, Oregon

ORIGINAL

Post (now missing) from which a:

6" Hemlock bears S25°W. 45 lks.; now 12" stub 8" high, scribes S BT visible, rest rotted off.

4" Vine maple bears N20°E. 20 lks.; now missing

RESTORED

Var. 21½°

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S35 S2 1956 RE2311," 33 inches in ground and from which a:


8" Fir bears S75°W. 45.8 ft.; scribed 1/4 S2 BT RE2311.

26" Cedar bears N17°E. 149.9 ft.; scribed 1/4 S35 BT.

Set 4" x 4" x 72" white painted cedar post 1.5' NW of pipe. Oregon State Board of Forestry metal location poster on 42" Fir Snag N66°E. 12.4 ft.

Dated March 19, 1956

Restored by Richard A. Morris under my direction.
Richard A. Morris, Transitman



Present and witnessed by: Robert Sturm
Lloyd Geraths
Warren Peterson
Ralph Schildknecht