

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 5, 6, 7 and 8, T. 3S., R. 7W., W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 6" Hemlock bears N.72°15'E. 7 lks.; now 13" stub 8" high, upper face burnt off, lower face charred with portion of scribe mark visible.
- 8" Hemlock bears S.47°E. 43 lks.; now 8" stub 1' high, scribe and face burnt off.
- 30" Hemlock bears S.46½°W. 40 lks.; now 32" snag, edges of burnt out upper and lower faces visible.
- 7" Hemlock bears N.68½°W. 16 lks.; now missing.

RESTORED

Var. 21½° E.

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3S R7W S6 S5 S7 S8 1957 RS359," 34 inches in ground, and from which a:


- 31" Fir stub 15' high bears N.39°W. 41.9 ft.; scribed T3S R7W S6 BT.
- 36" Fir snag bears N.6°E. 83.3 ft.; scribed T3S R7W S5 BT RS359.
- 38" Fir snag bears S.70°W. 36.3 ft.; scribed T3S R7W S7BT.
- 42" Fir stump bears S.43°E. 92.9 ft.; scribed T3S R7W S8 BT.

Oregon State Board of Forestry metal location poster on 42" Fir stump BT.

Set 3" x 5" x 60" white painted Cedar post 1' S.E. of pipe.

Dated April 24, 1957

Restored by Richard Morris under my direction.
Richard Morris, Transitman



Present and witnessed by Robert Sturm